Steel beams were installed around windows during White House renovation



Description

Central window of the north wall of the East Room, showing installation for a supporting steel beam running north and south through the East Room. The beam prevented the exterior walls from bulging during renovation work.

Date(s)

April 6, 1950

Accession Number 71-254

8x10 inches (21x26 cm) Black & White

Related Collection Harry S. Truman Papers

Keywords Building repair and reconstruction **Dwellings** Presidential residences

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.