

**Description**

View of southwest corner of the White House outside the Housekeeper's office (G-15) showing two completed concrete piers and form ready for pouring the cap of another. This photo was taken during the renovation of the White House.

Date(s)

February 23, 1950

Accession Number 58-531-016

8x10 inches (21x26 cm) Black & White

Keywords Building repair and reconstruction Dwellings Presidential residences Historic buildings
Renovation (Architecture)

HST Keywords White House - Exterior - Southwest corner; White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.