

# Bedroom and Sitting Room of the White House During the Renovation



## Description

Photograph taken in sitting room number 16 looking west into small bedroom number 17 at the northwest corner of the second floor of the White House. The studding between these rooms and the sub-flooring date from 1815-1818 when the White House was reconstructed after being burned by the British in 1814.

Date(s)

February 27, 1950

Accession Number

58-531-03

8x10 inches (21x26 cm)    Black & White

Keywords   Building repair and reconstruction    Dwellings    Historic buildings    Presidential residences    Renovation (Architecture)

HST Keywords   White House - Miscellaneous - Renovation

Rights   Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:**   Abbie Rowe    National Park Service    Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.