

**Description**

Southeast view from the West Sitting Room into Room 19. The steel girder, on the south side of the room, was installed in 1902 to support the floor by rods after removal of the old corridor wall below on the first floor to increase the size of the State Dining Room. From a series of photographs of the renovation of the White House.

Date(s)

February 20, 1950

Accession Number 58-531-080

8x10 inches (21x26 cm) Black & White

Keywords Building repair and reconstruction Dwellings Presidential residences

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.