

**Description**

View of west wall of State Dining Room. On the left is the old fireplace bricked up in 1902 when the new fireplace and mantel were erected to the north at the center of the wall. The extension of the flue to the main chimney is seen above the mantel. This is from a series of photographs of the renovation of the White House.

Date(s)

February 2, 1950

Accession Number 58-531-073

8x10 inches (21x26 cm) Black & White

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences
Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation; White House - Rooms - State Dining Room

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.