

**Description**

View of south wall of the West Sitting Room looking southeast into the Lincoln Room (Number 23) showing the original trusswork constructed in the period from 1815-1818. This is from a series of photographs of the renovation of the White House.

**Date(s)**

January 31, 1950

**Accession Number** 58-531-062

8x10 inches (21x26 cm)    Black & White

**Keywords** Building repair and reconstruction    Dwellings    Presidential residences

**HST Keywords** White House - Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe    National Park Service    Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.