

**Description**

View of south wall of Doctor's office in the White House, with partition being removed. Finished concrete underpinning columns with caps are seen on the left and at the right with original foundation in between.

Date(s)

February 16, 1950

Accession Number 58-531-053

8x10 inches (21x26 cm) Black & White

Keywords Building repair and reconstruction Dwellings Presidential residences Historic buildings
Renovation (Architecture) Offices

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.