

**Description**

Photo of Center Hall at the White House with a view of the cornice and book shelves added during the renovation, from an album of photographs by Abbie Rowe of the White House after the 1949 renovation.

**Date(s)**

July 31, 1952

**Accession Number** 82-57-108

8x10 inches (21x26 cm)      Black & White

**Keywords** Building repair and reconstruction      Dwellings      Presidential residences

**HST Keywords** White House - Rooms - Center Hall

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe      National Park Service      Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.