

View of west wall of the East Room at doorway to the main corridor of the White House during renovation



Description

View of west wall of the East Room at doorway to the main corridor of the White House during renovation. The design above the doorway dates from 1902. The iron above the doorway and the brickwork around it were installed in 1902.

Date(s)

March 1, 1950

Accession Number 71-200

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences
Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions

forms or provide additional paperwork. The Library charges no usage fees for downloaded images.