

**Description**

Southwest view from Main Corridor into entrance of the Blue Room during renovation of the White House. The archways and the brick walls on each side of the entrances to the Blue Room and Study (above) were taken down for installation of steel shoring columns. Between the Blue Room and Green Room on the north, the walls contained large openings as shown in the photograph.

Date(s)

March 17, 1950

Accession Number 71-235

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences
Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.