

Photograph of west wall of the Family Dining Room, during renovation of the White House



Description

Photograph of west wall of the Family Dining Room after plaster was removed showing studding dating from 1815-1818. Beyond the studding is the pantry (below) and the mezzanine (above). This photo was taken during the renovation of the White House.

Date(s)

March 7, 1950

Accession Number

71-216

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.