

Northwest view on second floor above the East Room during White House renovation



Description

Northwest view on second floor above the East Room, showing temporary steel columns for supporting the roof and third floor during the renovation work. The long steel beam below, running north and south above the central windows, was installed to support the walls and to prevent bulging during the work.

Date(s)

April 9, 1950

Accession Number 71-255

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Presidential residences Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.