

# View of center and east end of the second floor corridor of the White House during renovation



## Description

View of center and east end of the second floor corridor of the White House showing progress in installation of temporary steel showing columns. The entrance of study is on the right.

## Date(s)

April 10, 1950

**Accession Number** 71-256

8x10 inches (21x26 cm)      Black & White

**Related Collection** [Harry S. Truman Papers](#)

**Keywords** Building repair and reconstruction      Dwellings      Presidential residences      Renovation (Architecture)

**HST Keywords** White House- Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe      National Park Service      Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.