

# Southwest corner of the White House during renovation



## Description

Southwest corner of the White House during renovation. Workmen are installing form to pour concrete cap of column on this corner.

Date(s)

April 6, 1950

Accession Number  
71-252

8x10 inches (21x26 cm)    Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction    Dwellings    Presidential residences    Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe    National Park Service    Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.