

# View of North Hall of 3rd Floor Corridor during renovation of the White House



## Description

View of North Hall of 3rd Floor Corridor from the steps of the Sun Parlor on the south, taken during the renovation of the White House. From the temporary steel beams in the foreground, across the steel beams of the 3rd Floor, tie-rods were installed to hold up the 2nd Floor below.

## Date(s)

March 7, 1950

**Accession Number** 71-219

8x10 inches (21x26 cm)      Black & White

**Related Collection** [Harry S. Truman Papers](#)

**Keywords** Building repair and reconstruction      Dwellings      Historic buildings      Presidential residences  
Renovation (Architecture)

**HST Keywords** White House - Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe      National Park Service      Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.