

View along north wall from the south window of Room G-17 during renovation of the White House



Description

View along north wall from the south window of Room G-17 at the west end of the White House during renovation. Workmen are engaged in taking down the ceilings and walls of the basement rooms in this area. In the foreground is the east wall of Room G-18.

Date(s)

May 25, 1950

Accession Number 71-317

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences
Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.