

# Northeast view from the concrete beam during renovation of the White House



## Description

Northeast view from the concrete beam at the south central part of the White House showing the permanent and temporary supporting columns. The temporary horizontal beams, running from the north to the south wall, were installed to prevent walls from bulging during excavation below the basement level.

Date(s)

June 19, 1950

Accession Number  
71-330

8x10 inches (21x26 cm)    Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction    Dwellings    Historic buildings    Presidential residences    Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe    National Park Service    Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.