

# View along south wall looking west during renovation of the White House



## Description

View along south wall of the White House looking west from center of excavated area. The earth along the walls was left unexcavated until cross beams, running north and south, were installed to prevent walls from bulging.

## Date(s)

June 12, 1950

**Accession Number** 71-331

8x10 inches (21x26 cm) Black & White

**Related Collection** [Harry S. Truman Papers](#)

**Keywords** Building repair and reconstruction Dwellings Historic buildings Presidential residences  
Renovation (Architecture)

**HST Keywords** White House - Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.