

Photograph taken from Room G-6 during renovation of the White House



Description

Photograph taken from Room G-6 (Broadcasting Room) to east wall of building. The permanent steel columns and beams are partially completed to level of the Ground Floor and First Floor above. This photograph was taken during the renovation of the White House.

Date(s)

July 11, 1950

Accession Number
71-342

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.