

**Description**

View at the northwest corner, outside and below the north window of Room G-17, during the renovation of the White House. The installation is to test the strength of the foundation. The horizontal iron beams are supported by six vertical columns, below which is a two foot concrete foundation. Iron struts were erected to the wall at each side. A shift downward of 1/16" to 1/4" was recorded when four hydraulic jacks, each with a pressure of 50 tons, were applied to test the foundation.

Date(s)

July 26, 1950

Accession Number 71-347

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences
Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.