

# Wooden forms, wire, and iron around beams during White House renovation



## Description

Wooden forms, wire, and iron around beams being installed preparatory to pouring concrete floor of the Servants' Dining Room, and corridor on the south. View is to the north wall of this room. This was taken during the White House renovation.

## Date(s)

September 25, 1950

Accession Number 71-365

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.