

Northeast view of White House during renovation



Accession Number

71-258

Description

Northeast view of White House during renovation. The Seneca stone blocks of the wall leading from the portico to the northeast corner of the building were removed and the marked blocks stored on the lawn.

Date(s)

April 10, 1950

8x10 inches (21x26 cm)

Black & White

Related Collection

[Harry S. Truman Papers](#)

Keywords

Building repair and reconstruction

Dwellings

Presidential residences

Renovation (Architecture)

HST Keywords

White House - Miscellaneous - Renovation

Rights

Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit:

Abbie Rowe

National Park Service

Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.