Mud ruts and equipment from the oil pipeline



Accession Number 2008-493

9.25x7.5 inches Black & White

Related Collection Davies, Ralph K. Papers

Keywords Oil industries Pipelines

HST Keywords Pennsylvania

Rights The Library is unaware of any copyright claims to this item; use at your own risk.

Note: If you use this image, rights assessment and attribution are your responsibility.

Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.

Description

Mud ruts and equipment from the work on the oil pipeline in western Pennsylvania. To the right of the pipe was two D-8 boom cats working together. They help each other and other equipment out of the deep mud. The clam shell is clamming out a cave-in. From the Scrapbook War Emergency Pipelines, Inc.: Construction Views, Eastern Extension of East Texas-East Coast Pipeline Volume II.

Date(s)

ca. 1942