


Manchu Iron Works - Anshan, Manchuria



Description

Manchu Iron Works in Anshan, Manchuria. View of tapping side of Number 8 blast furnace. Of the nine furnaces at Anshan, Number 8, which had been undergoing repair just before the end of the war, is in best condition for resuming operation at an early date.

However, before it can be blown in, adequate blowing facilities must be installed and numerous parts must be "cannibalized" from some of the other eight furnaces in order to restore Number 8 to an operable condition. Photograph taken during the U.S. Reparations Mission. Edwin Pauley was the U.S. Ambassador on the Allied Reparations Committee from 1945-47 (the committee that assessed the reparations the Axis powers could afford to pay the victors).

Date(s)

June 12, 1946

Accession Number
2009-730

8x10 inches (21x26 cm) Black & White

Related Collection [Pauley, Edwin W. Papers](#)

Keywords Factories Reparations

HST Keywords China - Manchuria

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Marlin Fenical U.S. Army Signal Corps Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.