

# Unidentified Men Inspect a Spillway in Lind, Washington



## Description

Unidentified men inspect a spillway in Lind, Washington. On the back of the photo, Lyle Watts writes, "Lind, Wash. Rain of .13 inch on Jan 15, 1931 deposited 12 000 cu. ft. soil above dam filling dam to crest of spillway. Drainage area 871 acres. Soil was frozen at time of run-off. Maximum flow was 79 cu. ft. per sec."

Date(s)

ca.

January 15, 1931

Accession Number  
2009-2950

4x5 inches (10x13 cm) Black & White

Related Collection [Watts, Lyle Papers](#)

Keywords Landscape Water Forests and forestry

HST Keywords Washington - Lind

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Lyle Watts Forest Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.