

Modern Watch Tower Atop a the Skeletal Remains of a Fire Station in Nagasaki, Japan



Description

This is a photograph of a modern watch tower atop a the skeletal remains of a fire station in Nagasaki, Japan. Although the concrete block exterior remained after the bombing, the wood roof and interior as well as the non-fireproof windows have been destroyed by the fire. From Basil Rice.

Date(s)

October 1945

Accession Number 2018-117

4x5 inches (10x13 cm) Black & White

Keywords Fire stations War damage Nagasaki-shi (Japan) bombardment, 1945

Rights The Library is unaware of any copyright claims to this item; use at your own risk.

Note: If you use this image, rights assessment and attribution are your responsibility.

Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.